

#### 4 Types of Building :

##### RCC Roofed Building

###### Ground Floor

1 x 6.23 x 6.25 x 3.65 (m)	1 class room
1 x 6.12 x 6.25 x 3.65(m)	1 class room
1 x 6.17 x 6.25 x 3.65 (m)	1 class room
1x 6.05 x 6.25 x 3.65 (m)	1 stair room(staff room)
1 x 6.27 x 6.25 x 3.65(m)	1 class room
1 x 6.16 x 6.25x3.65(m)	1 class room

###### First Floor

1 x 6.23 x 6.25 x 3.70 (m)	1 class room
1 x 6.12 x 6.25 x 3.70 (m)	1 class room
1 x 6.17 x 6.25 x 3.70 (m)	1 class room
1 x 6.27 x 6.25 x 3.70 (m)	1 class room
1 x 6.16 x 6.25 x 3.70 (m)	1 class room

###### Second Floor

1 x 6.23 x 6.25 x 3.70 (m)	1 class room
1 x 6.12 x 6.25 x 3.70(m)	1 class room
1 x 6.17 x 6.25 x 3.70(m)	1 class room
1 x 6.27 x 6.25 x 3.70(m)	1 class room
1 x 6.16 x 6.25 x 3.70(m)	1 class room

##### MP Tiled Roofed Building

1 x 30.00 x 6.00 x 3.60 (m)	5 rooms
-----------------------------	---------

Signature  
Designation



*Nero*  
Assistant Engineer,  
LSGD Section  
Vazhikkadavu

**TO BE FILLED BY THE INSPECTING OFFICER**

(Assistant Engineer)

- Name of the School : **Orphanage English Medium School - Palad**
- 1 Name of the Officer : NAVANEETH K
- 2 Location : Wandoor Education District, Nilambur Education Sub District.
- 3 Period for which the Certificate is issued : **2024-2025**
- 4 Types of Building : Details Overleaf
- 5 Nature of Defect if any
- |                                  |   |   |     |
|----------------------------------|---|---|-----|
| a) Foundation and Basement       | : | } | Nil |
| b) Super structure               | : |   |     |
| c) Doors and windows             | : |   |     |
| d) Wood work wrought and putup   | : |   |     |
| e) Roof                          | : |   |     |
| f) Flooring                      | : |   |     |
| g) Miscellaneous (Cracks if any) | : |   |     |
- 6 Any Major defects noticed which will render the building unsafe in any manner : Not Noticed
- 7 Whether maintenance work have been done properly : Yes
- 8 Whether the structure is sound or not for conducting classes : Sound to conduct classes under normal wind and weather conditions as on 29.05.2024 as far as could be seen externally.

- Note:-
- 1 The Stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc..
  - 2 Any additional observation if deemed necessary for the certificate may be furnished separately with the Certificate

Certified that the School was inspected by me on **29.05.2024** and found **FIT** to conduct Classes , for the period for the reason stated above.

Place: Vazhikkadavu  
Date: 29.05.2024

Signature

Designation



*Nav*  
**Assistant Engineer  
LSGD Section  
Vazhikkadavu**